



2359 Holton Road - Muskegon, Michigan 49445

TFE731-2C-2B

Serial #	TSN	CSN
P74224C	15502.9	10509

Inspections	Hours Accomplished	Hours Remaining
MPI	15502.9	2,100
Plenum	15502.9	2,100
4200 Hr CZI	15502.9	4,200
4200 Hr Fan Support	15502.9	4,200
4200 Accessory GB	15502.9	4,200

Part Number	Description	Cycles Since New	Cycle Limit	Cycles Remaining
3073563-2	Fan Rotor	2568	10000	7432
3072395-1	1 st LPC Rotor	6965	10000	3035
3072396-3	2 nd LPC Rotor	2104	10000	7896
3072397-3	3 rd LPC Rotor	2104	10000	7896
3075326-3	4 th LPC Rotor	0	20000	20000
3073398-2	HPC Impeller	4515	10000	5485
3075814-1	HPT Rotor	0	10000	10000
3072070-5	1 st LPT Rotor	2104	4400	2296
3072069-5	2 nd LPT Rotor	2568	4500	1932
3072068-3	3 rd LPT Rotor	0	9500	9500

HPT Blades	Marks remaining 9
LPT #1 Blades	Marks remaining 9
LPT #2 Blades	Marks remaining 9
LPT #3 Blades	Marks remaining 38 each 9 marks remaining, 42 each 5 marks remaining

- Fresh MPI performed by Honeywell.
- Fresh CZI performed by Honeywell.

For Engine Support Contact:

CECIL SLOAN
csloan@aerovi.com
 Cell (972) 890-1001
 Fax (231) 719-2450

JEFF BARDAL
jbardal@aerovi.com
 Cell (817) 807-7945
 Fax (231) 719-2450

CARIE ANDREE
candree@aerovi.com
 Tel (231) 719-2350
 Cell (231) 557-1839
 Fax (231) 719-2450