

Visit our Website at [www.aerovi.com](http://www.aerovi.com)

RGB Module		TMM Module	
TSN:	13,976	TSN:	13,976
CSN:	14,601	CSN:	14,601
TSO:	2,743	TSO:	0
CSO:	2,904	CSO:	0
		TSHSI:	NA

- Overhauled by Vector Aerospace – January 2012 (4 week lead time)

Description	Part Number	Cycles Since New	Cycle Limit	Cycles Remaining	Cycles Remaining w/ Life Cycle Factor
HP Impeller	3043293	325	15,000	14,675	14,675
LP Impeller	3039487	0	15,000	15,000	15,000
Front Cover	3039640	2,904	15,000	12,096	10,139 / LCF 1.15
Rear Cover	3039639	5,354	15,000	9,646	9,646
HPT Disk	3041511	5,950	15,000	9,050	9,050
LPT Disc	3039412	0	15,000	15,000	15,000
PT1 Disk	3038513	14,601	30,000	15,399	15,399
PT2 Disk	3033914	14,601	30,000	15,399	15,399
Inter Stage Seal	3039172	2,904	15,000	12,096	9,096 / LCF 1.25
HPT Blades	3115601-01	1,538	15,000	13,462	13,462

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection;

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

JEFF BARDAL  
[jbardal@aerovi.com](mailto:jbardal@aerovi.com)  
 Tel (231) 799-9000 ext. 150  
 Cell (817) 807-7945

STEVE MCKEE  
[smckee@aerovi.com](mailto:smckee@aerovi.com)  
 Tel (231) 799-9000 ext. 151  
 Cell (231) 286-0448

EMILIO GOMEZ  
[egomez@aerovi.com](mailto:egomez@aerovi.com)  
 Tel (231) 799-9000 ext. 161  
 Cell (954) 809-8273

NICK BALDOCK  
[nbaldock@aerovi.com](mailto:nbaldock@aerovi.com)  
 Tel 011 44 1454 820082  
 Cell 011 44 7773 315567

KATHY RICHARDS  
[krichards@aerovi.com](mailto:krichards@aerovi.com)  
 Tel (231) 799-9000 ext. 38  
 Cell (231) 557-7923