

PW118 B ESN: 115646

TSN:	32,693
CSN:	45,484
TSO:	3,427
CSO:	4,693
TSHSI:	NA



Visit our Website at www.aerovi.com

Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	4,693	25,000	1.38	18,524
HP Impeller	3043294	4,693	15,000	0.83	11,105
LP Disk	3036412	4,693	25,000	1.667	17,177
Front Cover	3039640	4,693	15,000	1.354	8,646
Rear Cover	3039639	4,693	15,000	1	10,307
Inter Stage Seal	3039172	4,693	15,000	1	10,307
HP Disk	3041511	4,693	15,000	1	10,307
PT1 Disk	3038613	15,647	30,000	1	14,353
PT2 Disk	3033914	15,647	30,000	1	14,353
HP Blades	3115601-01	4,693	15,000	1	10,307

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

JEFF BARDAL
jbardal@erovi.com

Tel (231) 799-9000 ext. 150
Cell (817) 807-7945

STEVE MCKEE
smckee@erovi.com

Tel (231) 799-9000 ext. 151
Cell (231) 286-0448

EMILIO GOMEZ
egomez@erovi.com

Tel (231) 799-9000 ext. 161
Cell (954) 809-8273

NICK BALDOCK
nbaldock@erovi.com

Tel 011 44 1454 820082
Cell 011 44 7773 315567

KATHY RICHARDS
krichards@erovi.com

Tel (231) 799-9000 ext. 38
Cell (231) 557-7923