

PT6A-135A
Engines A1 & A2



TSN:	2,037.1
CSN:	2,038
TSO:	N/A
CSO:	N/A
TSHSI:	102.1

Visit our Website at www.aerovi.com

Life Limited Components

Part Number	Description	Cycles Since New	Cycle Limit	Cycles Remaining
3013111	Compressor Hub	2,038	19,000	16,962
3013712	2 nd Stage CT Disk	2,038	24,000	21,962
3011713	3 rd Stage CT Disk	2,038	25,000	22,962
3027798	Impeller	2,038	19,000	16,962
3024211	CT Disk	2,038	16,000	13,962
3022312	PT Disk	2,038	30,000	27,962

- HSI by Southwest Aviation 11/2010

LEGEND: TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

NOTE: ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION.

JEFF BARDAL
jbardal@erovi.com
Tel (231) 799-9000 ext. 150
Cell (817) 807-7945

STEVE MCKEE
smckee@erovi.com
Tel (231) 799-9000 ext. 151
Cell (231) 286-0448

EMILIO GOMEZ
egomez@erovi.com
Tel (231) 799-9000 ext. 161
Cell (954) 809-8273

NICK BALDOCK
nbaldock@erovi.com
Tel 011 44 1454 820082
Cell 011 44 7773 315567

KATHY RICHARDS
krichards@erovi.com
Tel (231) 799-9000 ext. 38
Cell (231) 557-7923