



2359 Holton Road - Muskegon, Michigan 49445

## TFE731-2C-2B

Serial #	TSN	CSN
P74223C	15073.2	10383

Inspections	Hours Accomplished	Hours Remaining
MPI	14126.3	1153.1
Plenum	14126.3	1153.1
4200 Hr CZI	14126.3	3253.1
4200 Hr Fan Support	14126.3	3253.1
4200 Accessory GB	14126.3	3253.1

Part Number	Description	Cycles Since New	Cycle Limit	Cycles Remaining
3073563-2	Fan Rotor	2787	10000	7213
3072395-1	1 <sup>st</sup> LPC Rotor	2339	10000	7661
3072396-1	2 <sup>nd</sup> LPC Rotor	2339	10000	7661
3072397-1	3 <sup>rd</sup> LPC Rotor	2339	10000	7661
3075326-3	4 <sup>th</sup> LPC Rotor	667	10000	9333
3075765-1	HPC Impeller	667	10000	9333
3075772-1	HPT Rotor	667	5200	9333
3072070-5	1 <sup>st</sup> LPT Rotor	2787	4400	1613
3072069-5	2 <sup>nd</sup> LPT Rotor	2787	4500	1713
3072068-3	3 <sup>rd</sup> LPT Rotor	3999	9500	5501

HPT Blades	
LPT #1 Blades	83 blades with 3 marks; 3 blades with 1 mark
LPT #2 Blades	84 blades with 3 marks
LPT #3 Blades	80 blades with 3 marks at 14126.3

**For Engine Support Contact:**

**CECIL SLOAN**  
[csloan@aerovi.com](mailto:csloan@aerovi.com)  
 Cell (972) 890-1001  
 Fax (231) 719-2450

**JEFF BARDAL**  
[jbardal@aerovi.com](mailto:jbardal@aerovi.com)  
 Cell (817) 807-7945  
 Fax (231) 719-2450

**CARIE ANDREE**  
[candree@aerovi.com](mailto:candree@aerovi.com)  
 Tel (231) 719-2350  
 Cell (231) 557-1839  
 Fax (231) 719-2450