

**PW118 B ESN: 115636**

<b>TSN:</b>	<b>34,559</b>
<b>CSN:</b>	<b>45,652</b>
<b>TSO:</b>	<b>3,788</b>
<b>CSO:</b>	<b>5,264</b>
<b>TSHSI:</b>	<b>NA</b>



Visit our Website at [www.aerovi.com](http://www.aerovi.com)

## Life Limited Components

Description	Part Number	Cycles Since New	Cycle Limit	Flight Count Factor	Cycles Remaining w/ Life Cycle Factor
LP Impeller	3040689	5,264	25,000	1.38	17,736
HP Impeller	3043294	5264	15,000	0.83	10,631
LP Disk	3036412	5,264	25,000	1.667	16,225
Front Cover	3039640	5,264	15,000	1.354	7,873
Rear Cover	3039639	5,264	15,000	1	9,736
Inter Stage Seal	3039172	5,264	15,000	1	9,736
HP Disk	3041511	5,264	15,000	1	9,736
PT1 Disk	3038613	16,302	30,000	1	13,698
PT2 Disk	3033914	16,302	30,000	1	13,698
HP Blades	3115601-01	5,264	15,000	1	9,736

**LEGEND:** TSN—Time Since New; CSN—Cycles Since New; TSO—Time Since Overhaul; CSO—Cycles Since Overhaul; TSHSI – Time Since Hot Section Inspection

**NOTE:** ALL DATA COMPILED IN THE CREATION OF THIS STATUS REPORT ARE FOR REFERENCE ONLY AND IS NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING THE CONTINUED AIRWORTHINESS OF THIS ENGINE. THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION

**JEFF BARDAL**  
[jbardal@erovi.com](mailto:jbardal@erovi.com)

Tel (231) 799-9000 ext. 150  
Cell (817) 807-7945

**STEVE MCKEE**  
[smckee@erovi.com](mailto:smckee@erovi.com)

Tel (231) 799-9000 ext. 151  
Cell (231) 286-0448

**EMILIO GOMEZ**  
[egomez@erovi.com](mailto:egomez@erovi.com)

Tel (231) 799-9000 ext. 161  
Cell (954) 809-8273

**NICK BALDOCK**  
[nbaldock@erovi.com](mailto:nbaldock@erovi.com)

Tel 011 44 1454 820082  
Cell 011 44 7773 315567

**KATHY RICHARDS**  
[krichards@erovi.com](mailto:krichards@erovi.com)

Tel (231) 799-9000 ext. 38  
Cell (231) 557-7923